
Fig. 1









Fig. 2





Stripping results in the SEZ spin etcher with various H2SiF6 concentrations.

Fig. 3
Residual polymers unstripped



10/516402

Fig. 4
After stripping with 100 ppm of H2SiF6




Fig. 5
After stripping with 500 ppm of H2SiF6




Fig. 6
After stripping with 1000 ppm of H2SiF6





Fig. 7
After stripping with 100 ppm of HF



Polymer residues and surface etching

Fig. 8
After stripping with 200 ppm of HF





Fig. 9 After stripping with 500 ppm of HF



Very great surface etching Stripping results in a Mattson AWP tank processor with various H2SiF6 concentrations.

Fig. 10
After stripping with 100 ppm of H2SiF6




Fig. 11
After stripping with 600 ppm of H2SiF6






Fig. 12: Result after use of a composition with added surfactant.



10/518463

Fig. 13
Comparison with Fig. 12: Result after use of a composition without added surfactant.



This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
☐ BLACK BORDERS	
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	
☐ FADED TEXT OR DRAWING	
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING	
☐ SKEWED/SLANTED IMAGES	
COLOR OR BLACK AND WHITE PHOTOGRAPHS	
GRAY SCALE DOCUMENTS	
☐ LINES OR MARKS ON ORIGINAL DOCUMENT	
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY	

IMAGES ARE BEST AVAILABLE COPY.

☐ OTHER: __

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.